



1992 DASSAULT FALCON F50 SERIAL NUMBER 228, N395HE

AIRFRAME: TOTAL TIME: 8254 HOURS

LANDINGS: 5505 CYCLES

ENGINES: **HONEYWELL TFE-731-4-1C** (STC -4 ENGINE UPGRADE)
8176/8119/8111 HOURS TOTAL TIME
5017/5015/5075 CYCLES SINCE NEW
MSP GOLD ENGINE PLAN

APU: HONEYWELL GTCP36-100A
4222 HOURS TOTAL TIME
MSP GOLD MAINTENANCE PLAN

AVIONICS: **COLLINS PROLINE 21 AVIONICS**
DUAL COLLINS AFD-3000 EFIS
DUAL COLLINS FMS 6200
DUAL COLLINS VHF-4000 COMM WITH 8.33/FM IMMUNITY
DUAL COLLINS VIR-4000 NAVS
DUAL COLLINS ADF-4000
DUAL COLLINS DME-4000
DUAL COLLINS TDR-94D TRANSPONDERS WITH **TCAS II 7.1**
COLLINS IFIS-5000 (INTEGRATED FLIGHT INFORMATION SYS) WITH ACARS/UNIVERSAL WEATHER
COLLINS APS-4000 AUTOPILOT
HONEYWELL LASEREF II WITH **WAAS/LPV**
COLLINS CTL-23D STANDBY NAV/COMM
DUAL COLLINS GPS-4000
DUAL COLLINS ADC-3000 AIR DATA COMPUTER
DUAL HONEYWELL HF-9000 WITH SELCAL
ALLIED SIGNAL MARK V EGPWS
COLLINS TWR-858 COLOR RADAR
COLLINS ALT-4000 RADAR ALTIMETER
L3 GH-3000 ELECTRONIC 3" STANDBY ALTIMETER
DUAL COLLINS AHRS AHC-3000
FLIGHT DISPLAY SYSTEMS FD-200 MOVING MAP

FEATURES: PRECISE FLIGHT PULSELITE SYSTEM
SECURAPLANE
STANDBY BATTERIES
FAIRCHILD A-100 COCKPIT VOICE RECORDER
PROVISIONS FOR FLIGHT DATA RECORDER

MAINTENANCE: 2C CHECK DUE JUNE 2028
DRY BAY MOD MARCH 2016
NEW PILOT AND COPILOT WINDSCREENS 2025
VERYON COMPUTER MAINTENANCE TRACKING

REMARKS: METICULOUS PART 91 U.S. OWNER/OPERATOR
NO KNOWN DAMAGE HISTORY
WILL CONSIDER A TRADE FOR A FALCON 900EX

EXTERIOR: NEW PAINT JANUARY 2022 BY AEROSMITH AVIATION. WHITE WITH BLUE AND SILVER TRIM.

INTERIOR: 4 PLACE CLUB FORWARD, AFT 2 PLACE CLUB OPPOSITE 3 PLACE DIVAN. TAN LEATHERS AND FABRIC. CREW JUMP SEAT. AFT LAVATORY WITH SINK AND MIRRORED VANITY. GALLEY WITH MICROWAVE, WARMING OVEN, HOT LIQUID DISPENSER. VHS/DVD PLAYER, AM/FM/CD PLAYER. LED LIGHTING. SOFTGOODS WERE REFURBISHED 2016. **IF DESIRED BY PURCHASER, SELLER AGREES TO PAY FOR RECOVERING THE 6 LEATHER PASSENGER SEATS DURING THE PREBUY.**